

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. C-2205

Dated: 13/09/25

It is certified that the existing building Rajiv International School (name of the building or premises) at Mathura Delhi Road, NH-2, P.O. Chhatihara, Mathura (U.P.) (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+3	G+3				

The building is owned/occupied by Rajiv International School, Mathura (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Inspection (Name of Department/ Govt.) on 13/09/25 (date of inspection) in the presence of Mr. Manoj Agrawal, H.No. 6, Sec. 1, Shri Radha Puram Estate, Mathura (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 13/09/25 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

1. —
2. —
3. — NA —
4. —

Issued on 13/09/25 at Mathura by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: अपर खण्ड आराम नगर

Name: Amey Kumar

Designation: Assistant Engineer

Name & Address of Department/ Office: Upper Dir. Area, Mathura

**PRINCIPAL**  
Rajiv International School  
MATHURA

**CHAIRMAN**  
Rajiv International School  
Mathura